



# PRODUCT SAFETY RECALL



## PRODUCT

**Max Birt Sawmills - All H3.2/H4/H5 wet Treated Packet numbers starting with MBP or PK letters delivered to CARTERS in October 2021 (Prior months production are fine).** Specific pack numbers listed on the following page.

## DEFECT:

This recall has occurred due to a failure in the CCA treatment process provided by Max Birt's contractor, Lumbercorp, affecting less than 6% of treated volume delivered in October 2021. The product would still normally be fit for purpose in respect of its intended use, but is not treated to the standard represented and is therefore of inferior quality and requires recall and replacement.

Please note all other packets purchased are unaffected by the above issue.

Lumbercorp sincerely regrets any inconvenience caused to you due to this processing error that affected only a small percentage of timber treated in the timeframes specified, but there are good testing processes in place to detect these issues as they occur, and full steps have been taken to rectify the issue so it cannot be repeated.

## HAZARD:

There is potential for the product to fail due to inferior quality, therefore requires recall and replacement.

## WHAT TO DO:

Please contact your local CARTERS branch or Max Birt directly if you have purchased the product pack numbers listed on the following page.

## CONTACT DETAILS:

**Company:** CARTERS  
**Phone:** 0800 CARTERS  
**Email:** [feedback@carters.co.nz](mailto:feedback@carters.co.nz)

# PRODUCT SAFETY RECALL

## BRANCH SOLD & PACKET NUMBERS IMPACTED

Branch	Packet number	Product
Cambridge	MBP109701	150 x 50 (140 x 45) H4 MG SG8 SL 6.0
Cambridge	MBP109702	150 x 50 (140 x 45) H4 MG SG8 SL 6.0
Cambridge	MBP109710	150 x 50 (140 x 45) H4 MG SG8 SL 6.0
Drury	MBP109705	150 x 50 (140 x 45) H4 MG SG8 SL 6.0
Drury	MBP109706	150 x 50 (140 x 45) H4 MG SG8 SL 6.0
Drury	MBP109707	150 x 50 (140 x 45) H4 MG SG8 SL 6.0
Drury	MBP109709	150 x 50 (140 x 45) H4 MG SG8 SL 6.0
Drury	MBP109760	150 x 50 (140 x 45) H4 MG SG8 SL 4.8
East Tamaki	MBP109743	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Glenfield	MBP109739	150 x 50 (140 x 45) H4 MG SG8 SL 4.8
Glenfield	MBP109729	150 x 50 (140 x 45) H3.2 MG SG8 SL 5.4
Glenfield	MBP109731	150 x 50 (140 x 45) H3.2 MG SG8 SL 5.4
Glenfield	MBP109388	100 x 50 (90 x 45) H3.2 MG SG8 SL 6.0
Hamilton	MBP109749	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Hastings	MBP109761	150 x 50 (140 x 45) H3.2 MG SG8 SL 4.8
Hastings	MBP109473	150 x 50 (140 x 45) H3.2 MG SG8 SL 4.2
Hastings	MBP109486	150 x 50 (140 x 45) H3.2 MG SG8 SL 4.2
Henderson	MBP109464	150 x 50 (140 x 45) H3.2 MG SG8 SL 5.4
Henderson	MBP109704	150 x 50 (140 x 45) H3.2 MG SG8 SL 5.4
Kaitaia	pk784413	50 x 50 (45 x 45) H3.2 MG No1 CTL 1.2
Kapiti	MBP109713	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Kapiti	MBP109711	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Kerikeri	MBP109459	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Mangawhai	MBP109462	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Masterton	MBP109721	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Masterton	MBP109750	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Napier	MBP109738	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Napier	MBP109450	150 x 50 (140 x 45) H3.2 MG SG8 SL 5.4
New Plymouth	MBP109488	150 x 50 (140 x 45) H3.2 MG SG8 SL 4.2
New Plymouth	MBP109482	150 x 50 (140 x 45) H3.2 MG SG8 SL 4.2
Onehunga	MBP109757	150 x 50 (140 x 45) H3.2 MG SG8 SL 4.8
Panmure	MBP109744	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Panmure	MBP109456	150 x 50 (140 x 45) H3.2 MG SG8 SL 5.4
Panmure	MBP109401	100 x 50 (90 x 45) H3.2 MG SG8 SL 4.8
Papakura	MBP109490	150 x 50 (140 x 45) H3.2 MG SG8 SL 4.2
Papakura	MBP109483	150 x 50 (140 x 45) H3.2 MG SG8 SL 4.2
Papakura	MBP109476	150 x 50 (140 x 45) H3.2 MG SG8 SL 4.2
Papakura	MBP109720	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Papakura	MBP109717	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Porirua	MBP109732	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0



# PRODUCT SAFETY RECALL

## BRANCH SOLD & PACKET NUMBERS IMPACTED CONTINUED

Branch	Packet number	Product
Porirua	MBP109728	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Pukekohe	MBP109746	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Rotorua	MBP109773	150 x 50 (140 x 45) H3.2 MG SG8 SL 3.6
Rotorua	MBP109776	150 x 50 (140 x 45) H3.2 MG SG8 SL 3.6
Rotorua	MBP109449	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Rotorua	MBP109461	150 x 50 (140 x 45) H3.2 MG SG8 SL 5.4
St Lukes	pk784321	50 x 50 (45 x 45) H3.2 MG Clears CTL 1.2
St Lukes	pk784330	50 x 50 (45 x 45) H3.2 MG Clears CTL 1.2
St Lukes	MBP109726	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
St Lukes	MBP109716	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
St Lukes	MBP109727	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
St Lukes	MBP109722	150 x 50 (140 x 45) H3.2 MG SG8 SL 5.4
St Lukes	MBP109736	150 x 50 (140 x 45) H3.2 MG SG8 SL 5.4
Tauranga	MBP109708	150 x 50 (140 x 45) H3.2 MG SG8 SL 5.4
Tauranga	MBP109378	100 x 50 (90 x 45) H4 MG SG8 SL 6.0
Tauranga	MBP109455	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Tauranga	MBP109391	100 x 50 (90 x 45) H3.2 MG SG8 SL 5.4
Waipakurau	MBP109733	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Warkworth	MBP109454	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Wellington Central	MBP109730	150 x 50 (140 x 45) H3.2 MG SG8 SL 4.8
Whangaparaoa	MBP109734	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Whangaparaoa	MBP109735	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Whangaparaoa	MBP109466	150 x 50 (140 x 45) H3.2 MG SG8 SL 4.8
Whangaparaoa	MBP109468	150 x 50 (140 x 45) H3.2 MG SG8 SL 4.8
Whangarei	MBP109475	150 x 50 (140 x 45) H3.2 MG SG8 SL 3.6
Whangarei	MBP109487	150 x 50 (140 x 45) H3.2 MG SG8 SL 3.6
Whitianga	MBP109458	150 x 50 (140 x 45) H3.2 MG SG8 SL 6.0
Whitianga	MBP109478	150 x 50 (140 x 45) H3.2 MG SG8 SL 4.2
Whitianga	MBP109480	150 x 50 (140 x 45) H3.2 MG SG8 SL 3.6